

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

27th June, 1938.

Dear Sirs,

E.

I am in receipt of your letter of the 23rd instant in further reference to the pumping arrangements in the case of Messrs. Lithgows' Yard No.906, and in reply have to say that the oil gutterway in the hold may drain into the hold bilges and any oil can be dealt with by the ordinary hold bilge suction.

I have to add it is not necessary to fit separate suction led to the transfer pump unless such an arrangement is desired.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,

GREENOCK.



© 2020

Lloyd's Register  
Foundation

W1163-a196