

Lytham report No 10239

TELEGRAMS:
CORRUGATED
MOTHERWELL.

SPECIALTY: CORRUGATED FURNACES.

TELEPHONE:
MOTHERWELL 176

THE BROOMSIDE BOILER WORKS COY LTD
CAMP ROAD,
MOTHERWELL,
LANARKSHIRE.

20th August 1934.

To: For shipment on account of The Steel Company of
Scotland Ltd., Glasgow.

Mark: M/S 258

Order No. ~~602/H.1023.~~
H. 532/H.1023.

Our Job No. 599


For Messrs Eriksbergs Mek. Verkstads, A-B.
Gothenburg.

4 "Morison" section CORRUGATED FURNACES, with Stephen Courlay
back ends. 7 ft 5.25/32" long x 2 ft 11 1/2" int. dia. x
13/32" thick.

Plates by The Steel Company of Scotland Ltd.

Nos. 2/ 650, 2/649.

The Plates have been subjected to mechanical tests and the Furnaces passed
for workmanship and found satisfactory by the Surveyor.



Lloyd's Register
Foundation

W1165 - 6146

THE BROOMSIDE BOILER WORKS COY LTD
CAMP ROAD
MOTHERWELL
LABARSHIER

Order No

10239

ALEXANDRA HOECH

Alexandra
Hoech



© 2020

Lloyd's Register
Foundation