

U. Yk rfts ^{and} 42830/33

Cracks in butt welds bottom
shell ~~at~~ stop can surveyors suggest
cause for similarity damage stop
have you knowledge of similar
cases affecting arrangement butts
in line different strakes

© 2021

Lloyd's Register
Foundation

W1166-0118