

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

SHIP'S NAME

'DONAX'

Rpt.

Slb.

No. *59977*

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

First Entry Report.

is submitted before this case receives the consideration of Committee, the Glasgow Surveyors be informed is concluded the end thicknesses of the bottom and shell plating are as indicated on the plan of ship section 'as built' and not as reported, but should be confirmed.

18.7.38



© 2020

Lloyd's Register
Foundation

W1168-0278