

Messrs. Lithgows, Ltd. Nos.939/40

"Y" Type Emergency Ships

It is submitted the Glasgow Office be informed that the scantlings of the Tween deck bulkheads proposed have been examined and found to be in order except in the case of Bulkhead No.66, which should be amended as indicated in pencil. The bolted plates for closing the tonnage openings should be framed, ~~and the hook bolts~~ ^{and} ~~should be 1" diameter.~~ These ~~doors~~ should be hose tested with the remainder of the bulkheads on completion.

JRL

22nd November, 1939.

Mr. 17.11.39
Amnd. 22.11.39
1 plan.

[Signature]



© 2020

Lloyd's Register
Foundation

W1161 - 0204