

Chief Surveyors _____

Received from Chief Surveyors _____

Ship's NAME SPRINGBANK

Report Lw.

No. 113535

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

of Survey _____

Condition

When due —

Noted

CEL 15.12.39

This vessel has been taken over by the Admiralty (Warship Production Dept) & is undergoing extensive alterations.



© 2021

Lloyd's Register
Foundation

W1170-0006