

"EMPIRE BEAUMONT"

Mdb. Rpt. No. 17278.

It is submitted before this case receives the consideration of the Committee, the Surveyors be requested to state whether the bottom in way of the Boiler Room tank has been cemented and whether hatch covers have been fitted at the 2nd deck. In this connection they should be referred to Section 32, clause 1 (b), and Circular Classing Letter 17.12.40.

16.7.42.

which please return when done with

DS

434 52-46-6

2 48

4 54

5 85

2 52

7 85

4 60

44

44

1003

2 85

1003

42

1078

58

6 52

44 52/40

173

W 1173-0062