

ss Tonnage 234.15  
ister Tonnage 273.70

of beam at side of uppermost continuous  
deck. See Sec. 3 (1c) ..... } D 10-5  
1st Longitudinal Number (L x D)..... = 1828

Owners J.E. Evans  
Managers

SOUTHAMPTON 3923.




# Lloyd's Register of Shipping,

31-32, Oxford Street,

Southampton, 5th March, 1936.

The Secretary,  
LONDON.



Dear Sir,

We beg to return as requested, Grimsby Report No. 19605 and note that they will be returned to us in the course of a day or two.


We are, Dear Sir,

Yours faithfully,

*J. Cunningham*

ENCLOSURE.

pro The Surveyors.



© 2020

Lloyd's Register  
Foundation

to REVISIONS, NO. each side .....

thickness of Intercoastal Plate...

Angles

Fourth Deck, amidships, Angle, [ ] or [ ] .....

Spacing.....



Referred to Mr. Spinka.

*SP*

6 - MAR 1936

Noted  
H.W.C.  
Ebb of 3.  
YRM

Return reports



© 2020

Lloyd's Register  
Foundation