

which it appears that engine No. 35960 made by Motorenwerke

59

per glass

inside.

235.

BOARD REPORT on the

"Arthurstown"

The Mark Lane Board of Trade Surveyors advised this office early this morning that trouble is being experienced with the steering gear, and members of the crew have complained. The vessel is leaving Charlton on the Thames for the Ordnance Wharf at Greenwich for loading and sails tomorrow morning. Mr Shaw of the London Surveyors was advised and he has the case in hand.

W.B.
22/10/36.
Lloyd's Register
W1176-0202