

Part of the electrical
equipment repaired

It is requested that
this vessel be eligible to
receive as ULASSED.

DM
29/2/44



© 2020

Lloyd's Register
Foundation