

Lloyd's Register of Shipping.



*St. Lawrence metal
Marine Works inc Hull 67
mv. MAYELEN
(ex Ottawa MAYELEN)*

Port MONTREAL, Que.

August 26th, 1946.

This is to Certify that

T.O. MORRIS

the undersigned Surveyor to this Society did at the request of
Messrs. Dominion Bridge Co. Ltd., Lachine, P.Q.
attend their Works on the 20th June, 1946
& subsequently for the purpose of
inspecting and testing One air receivers,
made to the order of Messrs. Wartime Shipbuilding Ltd.
and intended for "C" Type Coasters building at Morton Eng. & D.D.Co.Ltd.

The material has been tested as required by the rules, and the
scantlings of the air receiver are in accordance with the approved plan.

Each air receiver was, in the presence of the undersigned, tested
by hydraulic pressure to 425 lbs. per square inch and
found satisfactory.

PARTICULARS

RECEIVER NUMBER.	LENGTH. Ft. Ins.	INTERNAL DIAMETER. Ins.	THICKNESS In.	TENSILE STRENGTH. Tons Per Sq. In.	ELONGATION. % in. 8 Ins.	BENDS. Degrees.
B.1889J	7'-2"	22"	SHELL 5/16" HEADS 13/32"	29.6 28.1	25 29	180° 180°

Identification Mark:

No.	<u>4728</u>
LLOYD'S TEST.	
	<u>425</u> Lbs.
W.P.	<u>250</u> Lbs.
	<u>9-8-46 TOM</u>

(Signed) T.O. MORRIS

Surveyor to Lloyd's Register.

Fee £ : :

Int'l. Bp 20216987

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."