

15c,10,41.

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor..... 1928 JAN 1942

VESSEL'S NAME ..... THERMOPYLAE ..... Rpt. .... Syd ..... No. .... 18541

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

*Exp 11915 (9.28)*

The class is subject to slightly indented shell plating (p.s.f) being dealt with at the Owners' convenience.

The SYDNEY N.S.W. Surveyors report the vessel placed in dry dock, bottom coated, and a number of defective rivets in bottom plating renewed.

It is submitted the vessel appears worthy to remain as classed with record of survey 11.41, subject as above.

100A1 )  
With fbd ) Subject etc.  
11.41 Syd )

*CSM*  
*26-1-42.*



© 2020

Lloyd's Register  
Foundation

W1179-0203