

Rpt. 7.

For the information of Surveyors and the Committee only.

Received at

Office,

19

# Lloyd's Register of Shipping.

(Report on Machinery, No. 50584)

Port

HULL.

No. \_\_\_\_\_ ENGINE FORGINGS OR CASTINGS.

I have to report that the ~~Forgings or~~ Castings, as herein described, manufactured by Messrs Wm Broady & Sons of Hull for the Engines No. \_\_\_\_\_ being constructed by \_\_\_\_\_ of \_\_\_\_\_ for the Ship No. \_\_\_\_\_, being built by \_\_\_\_\_ of \_\_\_\_\_ have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects. These have been despatched to the vessel "Matsington Court"

Mark on ~~Forgings or~~ Castings.

*H. Cluis Juniper*

*Hull 2/9/40*

Lloyd's  
No. 957  
*RS & MC*

	CRANK SHAFT.	THRUST SHAFT.	INTERMEDIATE SHAFT.	TUBE SHAFT.
	FLYWHEEL SHAFT.			SCREW SHAFT.
Material* ... ..	/			
How made ... ..				
If Annealed ... ..				
Dimensions, Forgings				
Weight, Castings ... ..				
Progress on } Inspection { ... ..				
Tests on Standard Test Pieces.				
Tensile Test— Tons per square inch ... ..				
Extension per cent ... ..				
Cold Bending Test— Angle before fracture ... ..				
Dates when Inspected				

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:—

*Three 4 in. Castings for Double Check Valves for the vessel Matsington Court Examined & hydraulically tested to 500 LBS sq"*

Fee (if any chargeable) £

To be paid at

\* If of wrought iron, state whether piled bars or scrap. If of steel, state whether made by the Open Hearth process.

10m.9.27.



© 2021

Lloyd's Register  
Foundation

W1182-0092

Special Damage or Repair fee (if any) .....  
(per Section 29.)

Received by me,

*W. J. Shula*  
Engineer Surveyor