

COPY.

Lloyd's Register of Shipping.

Port KARACHI.18th MARCH 1944.

This is to Certify that

COMMANDER (E) G. S. MISKIN, R. I. N., J. P.,

the undersigned Surveyor to this Society did at the request of the agents and Ship Master attend on board the s. s. "City of Adelaide" Official Number 143683 Gross tonnage 6589 Port of Registry Liverpool on 16th March 1944 and subsequent dates while the vessel lay afloat in Karachi Harbour to survey the damaged hull plating in No.1 Hold.

My survey revealed that 39 frame rivets in way of Nos.11, 12 and 13 frame and adjoining stringer plate were slacked and 7 rivets in the stringer plate and frame bracket had sheared.

My recommendations are for the slack frame rivets to be caulked inside and outside and the 7 bracket rivets to be renewed.

A cement box to be fitted between Nos.11, 12 & 13 frames in way of defective frames.

SURVEYOR TO LLOYD'S REGISTER,
Karachi.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."