

1m.10.33.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor 2 - JUL 1934

VESSEL'S NAME Steel Ss "SCHIELAND"

Rpt.

No.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

COMPLETION OF 2<sup>nd</sup> S.S. No. 1 (due 4.33)The 2<sup>nd</sup> S.S. No. 1

partly held at

Rotterdam

now completed, and the following repairs done (due to wear &amp; tear):-

Vessel placed in dry dock, bottom coated

It is submitted the vessel is worthy to remain as classed, with record of Survey 6.34 and notation of S.S. No 1 - 34 as recommended.

100 A.1.

6.34. Rot.

S.S. Rot No 1. 34.

The Certificate of Classification to be endorsed "Cargo buttons not fitted" and the same notation to be printed in the Register Book.

Y.E.S.  
29.6.34Lloyd's Register  
Foundation

1119-0179