

1 - JAN 1945

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "EMPIRE DACE"

REPORT M.O.W.T. No. 116

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

^{BARI}
The BRINDISI M.O.W.T. Surveyor reports (11.44) the vessel placed in dry dock and bottom coated.

On account of damage cause not stated ^{stem} and shell plating on (port and starboard) bows indented. Minor repairs effected. Permanent repairs are recommended at the first convenient opportunity.

It is submitted that this vessel is eligible to remain as classed with record of docking survey 11.44, subject as recommended.

11.44 Brindisi, subject.



© 2020

Lloyd's Register
Foundation

28.12.44

W1195-0186