



Lloyd's Register of Shipping,

Collingwood Buildings, Newcastle-on-Tyne.

1st September 1920

LLOYD'S REGISTER
LONDON.

RECD 2 SEP 1920

ANSR

Reference

S

The Secretary
London

Dear Sir

In reply to the inquiry in the
dampification letter of the 31st August
regarding the Steamer *Hioko* New Rpt
No 73457. I beg to inform you that
the watertight doors are in apparent
working order, and that the 15 fathom
length of towline is of 11" hump as
required, and report the element
error occurring

I am Dear Sir
Yours faithfully
W. C. J. Ireland.



© 2021

Lloyd's Register
Foundation

should be requested to state if this is no

Referred to the Chief Ship Surveyor.

15-2 SEP 1920

Also for Mr. S. J. Hill to note.

M
29.20

[Handwritten text, mostly illegible due to cursive script and overlapping lines.]

[Handwritten text, mostly illegible.]



© 2021

Lloyd's Register
Foundation

SEL'S
The ren
Trans
Fram
Long
Rule
be c