

DB 100 lb.

M.V. Nottingham

GL. 64614

It is submitted that before this case  
receives consideration the Surveyors should be  
requested to verify their figure of 15" for the  
diameter of the screw shaft, as the plan shows  
it to be 18".

18"



© 2019  
Lloyd's Register

14/11/41  
Foundation  
W1201-0128

compartment to another yes Is the Shaft Tunnel watertight yes Is it fitted with a watertight door yes  
If a wood vessel, what means are provided to prevent leakage of either fuel oil or of lubricating oil from saturating the woodwork yes Stroke - Drive yes

Various Packings

Additional:  
Various screws



© 2019

Lloyd's Register  
Foundation

AD

VIII. 35. 5000.

125-33

121

Fore peak tank,

After peak tank,

Deep tank. aft.

✓  
66-66

438

173

Boilers,

only

compar

If a w