

Harland & Wolff Ltd., Belfast.

Yard No. 1028.

1111, 1937.

F.E. (FBD.)

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "PALMA" Rpt. Bel No. 12953

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/32

1st Long. No. 15194 Depth "d" -
2nd Long. No. 41119 Proportions = L/D 11.19
Framing As approved Sheerstrake As approved
D to Weather dk 38'; D to 2nd dk 27.75'; D for scantlings 35.75' (i.e. 8' above 2nd dk)

In accordance with a recent decision of the Ministry of Shipping the tonnage opening has been closed and decreased freeboards corresponding with a draught of 12" in excess of that of a C.S.S. vessel have been assigned.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1 "With freeboard" "Carrying cargo oil FP above 150°F in forward deep tanks and tanks at sides of tunnel".

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.

2 Dks, 3rd deck except in No. 5 hold.
Cell DB 368' 1330t, DTsf 56' 760t, Tanks at sides of tunnel 252t, FPT 47t, FK, 7BH (Coll to W. dk, 6 to 2nd dk), 6 divisional W.T. BHs in /APT 206t.
Upper tween dks, pt. Asp., Lloyd's A & GP

F 43'
O.L. 450.3'
E.S.D

The class is assigned and maintained upon the understanding that the equipment will be made to accord with the requirements of the Rules when the present state of emergency has passed.

Insert in S.R.L:- (60 fms. c.c. to be supplied)

The Surveyors should be informed it is concluded hatch covers have been fitted at the third deck, but this should be confirmed.

as there is no statement to the contrary

T.O. CLOSED. (W.E.)

© 2019... 22.4.41

Lloyd's Register Foundation

W1201-0206

Stakes

DOUBLE BOTTOM.

Solid Floors, thickness and spacing 1/42" @ 31"

Spacing.....