

the remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Time of Receipt. 11-50

## TELEGRAM.

ST OFFICE



TELEGRAPHS.

Office Stamp.

Office of Origin and Service Instructions

Words

Charges



THIS FORM MUST ACCOMPANY ANY ENQUIRY RESPECTING THIS TELEGRAM

Received here at

Committee London.

breezy please hand  
icate to book 130 minutes  
brahtree

LOYDS REGISTER  
LONDON  
13 NOV 1914



© 2019

Lloyd's Register  
Foundation

BEAMS, Forecastle Deck, Angle, Bulb Angle,  
Plate, Tee Bulb, or Channel.....

Deck. Material and thickness



Referred to the Chief Ship Surveyor

CSA

NOV 13 1914

Mr Wood to note

Certificates sent to owners as desired 13/11/14 J.S.H.



© 2019

Lloyd's Register  
Foundation