

Less Crew Space
Less above Crown of
Engine Room
CANNAGE FOR FEES...

Length on deck from after part of stem to fore part of
stern post
226.56
2nd Number

226.56 Owners

Entered in Reg. Book
Lond
don
try lock
ks with Fla
s of Beams
ound of Be
Inches in Ship
4 1/2 x 2 1/2
8 x 4 1/2
8 x 4 1/2
5 3/4
4 1/2
Single
load
ches Ship
Inches in Ship
16
2
8 1/2
3
28 1/2
4 1/2 x 9
at 28
6
thud li
to 2 1/2
anks
3 x 3 x
2 1/2
3 1/2
side fr
9
5 x 2 1/2
22

LOYDS REGISTER
LONDON.

REQ 22 OCT 1906
ANSE

Time of Receipt

10713

TELEGRAM.



Stras & Greenaway, London.

POST OFFICE TELEGRAPHS.

Office Stamp.



If the Receiver of an Inland Telegram doubts its accuracy, he may have it repeated on payment of half the amount originally paid for its transmission, any fraction of 1d. less than 1/2d. being reckoned as 1/2d.; and if it be found that there was any accuracy, the amount paid for repetition will be refunded. Special conditions are applicable to the repetition of Foreign Telegrams.

Charges } £ s. d.
to pay }

landed
at

Dock St Dundee 9-15th

Received
here at

10.2


TO

Committee London

From
list

Hong report just received
builders but still awaiting
of tonnages Morrison

N.B.—This Form must accompany any inquiry made respecting this Telegram.



© 2019

Lloyd's Register
Foundation

Spacing	23	23
PILLARS, In 'tween Decks, Size and Spacing	2 3/8 @ 46	2 3/8 @ 46
" " Hold	3 5/8 + 3 3/8 @ 46	3 5/8 + 3 3/8 @ 46

" Tie Plates
" Deck, Material and thickness *teak*
Forecastle Deck Stringer Plate, brdth & thickness

5 x 2 1/2
22

Referred to Mr. Mayne.

af
K

OCT 22 1906



© 2019

Lloyd's Register
Foundation