

29 MAR 1932

Received from Chief Surveyors

Report to Chief Surveyors

VESSEL'S NAME Steel Sc.Sr. "BAN HONG LIONG" Report Lon. No. 97340a

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

2nd No. 2 **SURVEY PARTLY HELD.**

When due 3.31 When proposed to be completed

Portion of Survey held, &c.,

The 2nd S.S. No.2, due 3.31. has been partly held.

The Singapore Surveyor now forwards a letter from the Owners stating they regret to say that the Company have decided to withdraw the vessel from class.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class.

Insert ...

*[Handwritten signatures and initials]*  
 26.3.32

THIS



© 2019

Lloyd's Register Foundation

W1202-0259