

UNDERTAKING CASE.

24.4.32

Received from Chief Surveyors

29.7.32

E Sth. s.s. *GLADIATOR*

Report *X* No.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case at the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Second Special Survey No. 1 When due

7.30.

R.S. due 1.31.

Y.S. due 8.30.

? General Examination

The 2nd S.S. No. 1 became due 7.30.

The Owners have furnished the usual undertaking.

In reply to enquiry the Falmouth Surveyors state that the vessel is still laid up.

It is submitted for consideration whether, in view of the special survey being now two years overdue, the Society's Surveyors at Falmouth should be requested to arrange with the Owners for the vessel to be generally examined.

W 4/5

[Signature]

[Signature]

[Signature]

[Signature]
27.7.32



© 2020

Lloyd's Register
Foundation

W1212-0114