

4 JUL 1932

No. 33956

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report June 21 1932 When handed in at Local Office June 21 1932 Port of NEW YORK
No. in Reg. Book. Survey held at --- Date, First Survey --- Last Survey 19
(No. of Visits)

64666 24398 on the Wood, Iron or Steel S. S. 3 Mst. Sr. "J.A. MOFFETT"
TONNAGE: Built at San Francisco By whom Union Iron Works Co. When 1915 MONTH 3
GROSS 6521 Owners Standard Oil Co. of California Owners' Address
UNDER DK 5846 Managers Port belonging to San Francisco
NET 4012

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
WB=CellDBorDBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 6647 Port S. Fo.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as painted on Ship and now verified { ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

The Owners of this vessel have requested that she be withdrawn from classification with this Society (see copy of letter from Owners dated June 14th, 1932).

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Faired or Repaired ...								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Dbng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt).
Coamings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Beams & Fastenings	Ceiling	Scuppers	Boats
Outside Plating	Cement or Asphalt (State which.)	Cargo Hatchways	Masts, Yards, &c.
Breasthooks	Rudder	Hatches	Condition, how ascertained
Transoms	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)
Frames	Windlass	Caulking ditto	Sails
Reverse Frames	Have Pumps now been examined and found efficient?	Treenails ditto	Equipment letter
Longitudinals	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of
Transverses	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Floors	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	" length (on board) size
Keelsons		Ditto ditto at other places ditto	" Rule length size
Stringers		Stringers, Clamps & Shelves ditto	Hawser & Warps
Inner Bottom Plating		Salting (State if examined.) ditto	Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me.
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute

Character Assigned

LD. 8/7/32
L.M.K. 8/7/32

NEW YORK JUN 22 1932

Withdrawal and insert...

NOTES FOR POSTING

Surveyor to Lloyd's Register of Shipping.

General Committee

Thursday, 7th July 1932

American Committee

decision confirmed