

12 DEC 1932

Received from Chief Surveyors

Sent to Chief Surveyors

VESSEL'S NAME Steel Sc. "FOSSA"

Report Lon.

No. 98098a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.32.)

Nature of Survey

When due

Screw shaft due 9.32.

The Owners write that they do not propose to continue the classification of this tug.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class.

Insert ...

18/12/32



© 2020

Lloyd's Register

W214-0244