

1m,9,29.

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Sc. "P. ABOITIZ",

Report Lon. /

No. 97890a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey

When due

The 1st S.S. No.1 became due 6.32.

The Manila Surveyor now forwards a letter from the Owners stating that, as they have decided to withdraw the vessel from class, it is not necessary to make the survey at present.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class.

Insert ...



© 2020
6.10.32

Lloyd's Register
Foundation
WILIS-0309