

Are two independent means arranged for circulating water through the Oil Cooler

yes

Suctions, connected to both Ma

Pumps, No. and size:—In Machinery Spaces

1-2

1-2" in tunnel well

2 ad. n. E

0 0 1

1-24

16 0 1

W1215-0328

P. ADDITIZ

Alg. 6300.

It is submitted that  
this vessel is eligible for  
THE RECORD

+ LMC 6.28 CL.

OIL ENGINES. 4 SC. SA.  
6cy. 11-19 1/16 95NHP.

MOTOREN FABRIK DEUTZ A.G.  
COLOGNE-DEUTZ.

B.M. 25/7/28

Lloyd's Register  
Foundation

Can the internal surfaces of the receivers be examined

yes

What means are provided for cleaning their inner surfaces

Is there a drain arrangement fitted at the lowest part of each receiver

yes