

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

23rd October, 1930.

Dear Sir,

With reference to my letter of the 10th instant relative to the steamer "IRMA SCHINDLER", I have to acquaint you I am in receipt of a report from the Society's Surveyors at Philadelphia from which it appears that temporary repairs were carried out at Tampico in June last to a leak in the bottom on the port side of No.4 tank by fitting a bolted patch and cement box. This repair has now been examined by the Philadelphia Surveyors and they recommend that permanent repairs should be effected at Hamburg whither the vessel is proceeding.

In the circumstances I shall be glad if the Surveyors will give the case the necessary attention in due course.

I am, Dear Sir,

Yours faithfully,

A. Chisholm, Esq.,

HAMBURG.

pro Secretary.



© 2020

Lloyd's Register
Foundation

W12 77-0060