

(Received at London Office 16 NOV 1921)

No. 84852

REPORT of SURVEY for REPAIRS, &c.

Writing Report 16 NOV 1921

When handed in at Local Office 16 NOV 1921

Port of London

Survey held at Tilbury

Date, First Survey 7 November Last Survey 7 November 1921

(No. of Visits)

Master One

on the Wood, Iron or Steel J. S. S. Ormuy

TONNAGE:-

Built at Yegorack

By whom Bremer Vulkan

When 1914

SS 14167

Owners Orient S. N. G. L.

Port belonging to London

ER DK 9975

Owners' Address

(if not already recorded in Appendix to Register Book).

veyed Afloat or in Dry Dock? Yes

Name of Dock Tilbury

Destined Voyage

= Cell DBor DBa

feet; uE&B

feet; f

feet; f

Capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined. If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Report, No.

Port

CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.

Years
Assigned
expired.

Machinery and Boiler
Surveys
(including date of N.B., if any).

Local Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; repairs being detailed in the body of the report, should be summarised in the form shown below. Whenever the amount of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why were declined?

Was a damage report made by anyone else? If so, by whom?

RS, OR EXAMINATION AS PER RULE, FOR

Classification Survey further advanced. (See Rules by report 12412)

Now done - No 8 Tween decks examined and found satisfactory.

The owners representative states that the survey will be continued on the vessel return from her present voyage.

Y OF DAMAGE REPAIRS :-

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
awed								
moved and Paired or Repaired								
red or Repaired in place								

CONDITION OF THE

Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Inner Bottom Plating	Engine Room Skylights	(State if on Vell.)
State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
State if Tanks now tested	Scuppers	Boats
Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Ceiling	Hatches	Condition, how ascertained
Cement or Asphalt	Planking of Wood Vessels	(State if wedges removed)
(State which.)	Caulking	Sails
Rudder	Treenails	Equipment letter
Steering gear and its connections	Breasthooks & Stemson	Anchors, No. of
Windlass	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Have Pumps now been examined and found efficient?	Timbers of Frame at openings ditto	length size
Have Sluice Valves now been examined and found efficient?	Ditto ditto at other places ditto	(on board)
Have Watertight Doors now been examined and found efficient?	Stringers, Clamps & Shells ditto	Rule length size
	Salting	Hawser & Warps
	(State if examined.)	Standing & Running Rigging

ral Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

The above is reported for the information of the Committee

(per Section 25)	£	:	:	Fees applied for,
Page or Repair Fee (if any)	£	:	:	19
Expenses (if chargeable)	£	:	:	Received by me,
Surveyor's Fee (if any)	£	:	:	19

Norman Dotson

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

TUE. 13 DEC. 1921

Master Assigned

No action

TUE. 22 AUG. 1922

FRI. 13 APR. 1923

FRI. AUG. 31 1923

© 2019

Lloyd's Register Foundation

W1218 - 0150

Is Certificate required? If so, to be sent to