

1

'4 - MAY 1933

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel Sc. K. "BALIK" Report Lon No. 98684a**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey _____ When due _____

The Boiler Survey became due in 11,32.

In reply to enquiry the Istanbul Surveyor now forwards a letter from the Owners in which they state that this vessel will not continue in her class.

It is submitted the class of this vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class
Insert ...

[Handwritten signature]
3/5/33
[Handwritten signature]



© 2020

Lloyd's Register
Foundation

W1 223 0034