

Engine Room ... }
Gross Tonnage. 4896.27
Tonnage ... 178.36

Longitudinal Number ... 51492
Depth "d," at middle of length (See Secs. 2 & 13) ... 18.91

Owners. Rotterdam
Managers

TELEGRAMS:
OYDS REGISTER.

TELEPHONE:
Nº. 615.

Lloyd's Register of British & Foreign Shipping.

VEERHAVEN W. Z. 19. — ROTTERDAM.

BUSINESS LETTERS TO BE
ADDRESSED TO:
SHEPPARDSON & CO. LTD.
REGISTER.
ROTTERDAM.

19th April

1912.

The Secretary
London

Sir.

I have telegraphed to day:

Birma Bagasse by Owners. The new Steamer
Birma cannot sail without the Dutch Scheepvaart
Inspectie having received a letter or the Certificate
to prove that she holds a class with us.

The Owners informed me that they have not yet
received a Certificate and for that reason I have written
you as above.

In case the Certificate is not to hand please wire if
her classification is in order, to enable me to see the
Inspector of the Scheepvaart with regard to the issue of
their Certificates.

I am Sir,
Your obedient servant
P. J. Remmenburg.



© 2021

Lloyd's Register

Foundation

Spacing ... 51
BEAMS, Third and Fourth Deck, Single Angle,
Bulb Angle, Plate, Tee Bulb or Channel

Poop Deck Stringer Plate, breadth & thickness
Angle on ditto

Referred to Mr. Mayne.

Referred to Mr. Mayne.

7 Kue.

[Faint handwritten notes, possibly "Lloyd's Register"]

[Extensive handwritten text, likely a ledger or account, with various numbers and names.]

[Handwritten mark, possibly "10/11"]

[Handwritten mark, possibly "10/11"]

MACBETH

W. S. W. NEVILL

Register of British & Foreign Shipping

© 2021

Lloyd's Register Foundation



Do. of Houses on
Do. of excess of H
Do. above Crown
Engine Room
Gross Tonnage
New Space

BEAMS, Third a
Spacin
Publ

23507-23501. 500,000

accuracy of this
on application at

= COM

BS
BM