

In damage cases where the Surveyor has not made a special damage report he is required to state what...

13 AUG 1930

S.S. "GREGORY ZINOVIEFF".

The screwshaft survey became due 1,30.

In reply to enquiry, the Owners' Londen Agents new write that this steamer is in the Far East, and they cannot state when and where the survey can be carried out. They have, however, information from the Owners that this survey will be effected by the Register of the U.S.S.R.

IT IS SUBMITTED that in the circumstances the class of this vessel might be withdrawn from the Register Beek and three deta(...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...

[Handwritten signature]

[Handwritten signature]

--.14.8.30.



© 2021

Lloyd's Register Foundation

W1228-0109

Surveyor to Lloyd's Register