

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Stl T.S. Lug LOCH LONG Report Slc No. 45711**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Entry

When due

Revised Rules

✱ 100 A.1. (Steel) "For Towing Services"

1 D^o (Stb).

D.T. 5' 10t, A.P.T. 16t.

F^o, H.B.H., Cen., Lloyd's A. CP
113'.

© 2021

3.6.26

Lloyd's Register
Foundation

W232-0001

Solid Floors, thickness and spacing

" " Are Frame and Reversed Frame
" " Joggled ?

Bracket Floors, breadth and thick

Bridge Deck, Angle, E or F

Spacing