

REPORT of SURVEY for REPAIRS, &c.

No. in g. Book. Survey held at Glasgow Date, First Survey 24th March Last Survey 3rd April 1905
 on the Wood, Iron or Steel S.S. Queenie (No. of Visits 3) Master

TONNAGE:- Built at Workington By whom R. Williamson When 1905
 GROSS Owners A. H. Knap Ltd Port belonging to London
 UNDER DK. Owners' Address
 NET (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Yes Name of Dock Princes Destined Voyage
 WB=CellDBorDBa ✓ feet; uE&B ✓ feet; f ✓ feet; }
 total capacity ✓ tons; FPT ✓ tons; APT ✓ tons; MT ✓ feet ✓ tons. }
 N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

CHARACTER.	Years Assigned	Machinery and Boiler Surveys
100 A. 1		
<u>Class Contemplative</u>		

Last Report, No. ✓ Port ✓
 (Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)
 Society's Freeboard (if assigned) as painted on Ship and now verified } ✓ ft. ✓ ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? ✓ also whether any damage report was made, and, if so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR
The engine & boiler casings have been efficiently closed in & rivetted

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if icicles removed)
Caulking of ditto	Rudder	Caulking ditto	Sails
Rivets	Windlass	Treenails ditto	Equipment letter
Breasthooks & Crutches	Have Pumps now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of
Transoms	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	" length size
Reverse Frames		Ditto ditto at other places ditto	" Rule length size
Floors		Stringers, Clamps & Shelves ditto	(per Table 22)
Keelsons		Salting ditto	Hawsers & Warps
		(State if examined.)	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c. :-
 State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

The above is for the information of the Committee

Office Fee (if chargeable) per Scale II, Sec. 27	Survey Fee (per Section 28)	Special Damage or Repair Fee (if any) (per Sec. 28.)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Fees applied for,
£	£	£	£	£	19
					Received by me,
					19

Committee's Minute
 Character Assigned For the Committee's information.
 Glasgow 10 APR 1905
 FRI. 14 APR 1905
 P. H. MacKellar
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Is Certificate required? If so to be sent to W1237-0156