

Chief Ship Surveyor .....

Received from Chief Ship Surveyor 28 MAY 1930

NAME Steel S.S. "ANDIJK"

Rpt. Rot 19422  
Ham No. 19345

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Survey .....

The 2nd S.S. No.2 became due 9,29 and a proposal to carry out same on arrival at Rotterdam was agreed to in December last.


The Rotterdam Surveyors now report the vessel placed in drydock and bottom coated.

No part of the Special Survey has been held, but it is stated that the same will be carried out before the year of grace expires.

The Hamburg Surveyors now report that on account of damage through heavy weather, 1 shell plate has been renewed and 1 shell plate repaired with a doubling.

It is submitted action be deferred.

W. M. M. A.  
27.5.30.



© 2020

Lloyd's Register  
Foundation