

Gro
Less
Less
En

Andyk

F.E.

Received by Chief Ship Surveyor *15.2.09*

Received from Chief Ship Surveyor

VESSEL'S NAME *St. S. S. "Brantford"*

Rpt. *Rwc*

No. *56134*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>1/2" less on account of deep bulb angle framing being carried up to shelter deck.</i>	
Spar Sheerstrake . .	<i>✓</i>	<i>✓</i>
Description of Framing:— <i>Deep (Bulb angle) framing, 1/2" less in depth, (viz., ordinary, deep, zed, channel or bulb-angle). but compensated by increased thickness.</i>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100 A 1 ("Steel") "*Shelter deck* with freeboard," as recommended. The Summer freeboard of *4'-3"* from centre of disc to top of statutory deck line at *upper* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

\pm 100 A 1 ("Steel") "*Shelter deck with freeboard*"
2 Ds (Stl) & deep framing & shelter Dk (Stl)

N. B = Cell DB = 146' u E & B 47' f 169' 1137c DT = 36' 870c APT 38c

FK 7BH Gen. Plydgs 14 CP



© 2020

Lloyd's Register
Foundation