

COPY.

W1243-0170

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

CLOSURE.

9th February, 1931.

Dear Sir,

With reference to the correspondence which has taken place between us respecting the steamers "CAMBRIAN DUCHESS", "CAMBRIAN MAID" & "CAMBRIAN PEERESS", I am directed to acquaint you that as it would appear that these vessels are still laid up, the Committee can only agree to their classes in the Register Book remaining undisturbed for the present on the conditions set forth on the enclosed form, which I shall be obliged if you will kindly sign and return to me in due course.

I have to add that the 2nd Special Survey No.2 of the steamers "CAMBRIAN MAID" & "CAMBRIAN PEERESS" became due at the end of last month and, in the circumstances, the Committee are agreeable to these surveys being postponed for the present.

Further, in the case of the "CAMBRIAN PEERESS" repairs to two casing plates damaged through fire in the bunker require to be carried out at the first convenient opportunity, while in the case of the "CAMBRIAN MAID" the stern frame and rudder, repaired by electric welding 5,24 and 12,29, requires to be specially examined at the next drydocking, and some damaged shell plating etc., on the starboard side, permanently repaired.

I am, Dear Sir,

Yours faithfully,

Charles D. Ross, Esq.,
Messrs. C.D. Ross & Co.,
27, Old Jewry,
E.C.2.

copy to NWC
Secretary.

© 2020

Lloyd's Register
Foundation