

W1247-0257

Craig. As the Class is subject to the  
Donkey Boiler not being used  
the main Boilers have not been  
~~and~~ surveyed since 4.32. The Engineers  
would satisfy themselves as to the  
condition of the main Boiler which  
will be used on the passage.

my

2/9/33

Lloyd's Register  
Foundation