

Received from Chief Surveyors _____

M. Lunde 'ARABIC'

Report *Lv*

No. 96788

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case. The Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/4/03.)

Completion of 2nd S.S. N^o 2 When due *8.29*

Subject to indented shell plating &c being repaired as necessary at the Owners' convenience.

[Signature]

KAP
17.3.30



© 2021

Lloyd's Register
Foundation
W1248-0172