


Last Report, No. 7096 Port *Fal*+ A-
For Towing Purp
11.29TELEGRAMS: "BEDI, JAMNAGAR"
ComportTHE COMMISSIONER OF
PORTS AND CUSTOMS.BEDI PORT,
JAMNAGAR,
KATHIAWAR.

9th April 1931.

Ref.No./W.G./508

To,

H. P. Southwell Esquire.,

Surveyor to Lloyd's Register,

Exchange Building, Sprott Road,

Ballard Estate, Bombay.

Dear Sir,

In reply to your letter of the 3rd Instant, I beg to advise that the question of survey of the s.s. "Theydon" has been considered by the State and it has been decided not to retain this vessel in her class under Lloyd's Registry.



C.P.

Yours faithfully,

*W. G. B. Aune*Lieut. Comdr. R.N., F.R.G.S., A.I.N.A.
Port Commissioner,
Nawanagar State.

Items:—

Copper, or Y.M.
(State if on
When put on

Boats

Masts, Yards, &

Condition, how as

(State if rec

Sails.....

Equipment letter

Anchors, No. of

Cables (State if


,, length.....

(on board

,, Rule length

Hawser & Warps

Standing and Run

sel in the Register
remain as classed

© 2020

Lloyd's Register
Foundation

W1251-0189

10m.
Requested not to

Travelling Expenses (if chargeable)£

Second Surveyor's Fee (if any)£

19

Surveyor to Lloyd's Register

General Port