

COPY.

Translation of a cablegram sent to the Society's Surveyors at Piraeus on the 5th January 1933 by "H" Dept

DIONI	
OLJIM	- To entitle vessel to reinstatement of class
PIBYG	+ all requirements of 3rd S.S. No.1 remain to be complied with except
ROOGY	- examination of fore and after peak tanks
ROPMI	- examination of chain locker
ROFOS	- examination of decks
ROFYV	- examination of tween decks
ROFDE	- examination of tween deck bunkers
ROSCU	- examination of windlass
SAZME	- Stop
SYPAF	- Wasted
NEGBV	- tank top plating
SOVZE	- under
ALPFU	- boilers
ACPUN	- also
AKYZE	- shifting beams
ADIMT	- and
JUJWI	- fore and afters
MEKXH	- of
SOLVY	- tween deck
ETHFE	- cargo
KOFYA	- hatchways
OSOGD	- require to be repaired
SAZME	- Stop
RUKYG	- To complete machinery survey following remains to be done
RYLIJ	- examination of sea cocks and fastenings
NECKY	- indented shell plate
NAVVO	- plate No. -- in G strake
UHPEH	- 3
NELEB	- port side
OSGYP	- requires to be dealt with



© 2020

Lloyd's Register
Foundation

W1256-0250