

36745  
TONNAGE :-  
GROSS 4560

Built at *Sunderland*  
By whom *Salvatore Savio*  
Owners

21 JUN 1933

Chief Surveyors 19.6.33.

Received from Chief Surveyors

SHIP NAME *Ste. s.s. PRESTO*

Report *Haw* No. *20532*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - (Extract from Sub-Committee's Report, 24/5/32.)

*2nd* No. *2* SURVEY PARTLY HELD.

*11.30* When proposed to be completed

Survey held, &c. *Scantlings*

It is submitted the attached print of midship section, together with drilling sheets (2), be forwarded to the ~~Dunkirk~~ *Boulogne* Surveyor for his information.

The Surveyor should be requested to return the print of midship section to this Office when the survey has been completed.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

PLATING to be DRILLED when vessel is ~~21 years old~~ *de-docked* completion of this Special Survey thereafter.

*Cher*  
*20/6/33*  
*B.S.*

*For Mr Sprinds to note  
twice Bow (Copy to Dnk)*

*21.6.33*  
  
*W1258-0008*

© 2020  
Lloyd's Register  
Foundation

*...in my opinion to remain as classed and to*