

t.s.s. "SVEND FOYN"

4125- (2/24/53)

Boiler Survey (not due) has now been held and all the plain tubes renewed.

Six additional press boilers, built under special survey, have been fitted.

It is submitted the vessel is eligible to remain as classed with record of B.S. 8.33.

It is further submitted the Oslo Surveyors attention be drawn to the Secretary's letter of the 8th December last regarding the inspection of press boilers, and they should state why this matter has not been dealt with at this time.

As there is no information in this Office regarding the press boilers ^{originally} fitted, the Surveyors should state whether they were constructed under survey, and, if not, it will be necessary for them to make arrangements for the boilers to be examined in accordance with the instructions contained in the Secretary's letter of the 8th December last, on the vessel's return.

Delete Press Boiler Pressure

DA 23/9/53

See Oslo Report 4160 + 4160 + 4160 B
for see
this vessel
© 2020
Lloyd's Register Foundation
W126-009