

31 MAY 1934

t to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel Sc. "EIFEL"

Report

Lon

100106a

No

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

ture of Survey

When due

The Boiler Survey became due 3,34.

The Hamburg Surveyors forward a letter received by them from the Owners requesting the withdrawal of this vessel's classification from the Register Book.

It is submitted the class of this vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class

Insert ...

WAB
J.P.
31.5.34



© 2021

Lloyd's Register
Foundation

W1262-0003