

2m,10.33.

1

17 JUL 1935

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Sc.K. "EARLE" Report Lon, No. 101524a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)


Nature of Survey _____ When due _____

The 2nd S.S. No.2 became due 6,35.

In reply to the usual Notice the Owners write intimating withdrawal of the class of this trawler.

It is submitted the class of this trawler be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class
Insert ...



2020
15 July 35

Lloyd's Register
Foundation

W1269-0058