

10m, 11, 20.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *Steel S.S. "Superga."* Rpt. *Gen* No. *8307.*

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey *First Entry.*

To await Freeboard assignment.

In the meantime, it is submitted the Genoa Surveyor be requested to state:—

- 1) whether the upper Deck stringer plate at ends is as approved
- 2) whether the Bridge Dk. is plated as required by the Rules.
- 3) whether the thickness of the wood deck on the poop and forecastle decks is as approved for the poop deck or as reported.
- 4) whether the number of web frames in the after body is reported includes those in the E. & B. space.
- 5) whether the thickness of the shell plating at the ends is as reported or as shown on approved plan of shell expansion.
- 6) whether the propeller post is as approved or as reported.
- 7) whether means are provided for draining the crown of the deep tank forward, and fore peak tank top.
- 8) whether the test of the steam steel wire is as required by the Rules
- 9) whether the length of the forecastle is as shown on the approved plan or as reported.
- 10) the length and water ballast capacity of the deep tanks forward if used for water ballast and oil fuel.
- 11) whether a double bottom has been fitted under the machinery aft, and to state the length and capacity of same for inclusion in the Register Book.

*Gr. Gen. 17/1/23*

*W1274-0272*

© 2020

A.W.F.

Lloyd's Register Foundation