

4 MAR 1935

Rpt. 3.

(Received by ...)

REPORT OF SURVEY

Date of writing Report ... When handed in at Local Office ...

No. in Reg. Book. Survey held at Date, First Survey

83828 on the Wood Iron or Steel *RINA CORRADO*

TONNAGE Built at *Ballast* By whom *Harland & Wolff*
GROSS 5180 Owners *Corrado Soc Anon di Nav.* Owners' Address
UNDER DK 4815 Managers Port belonging to
NET 3125

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B. All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. *13787* Port *Gen*

Periodical surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Particulars of Classification (which must be precisely as in Register Book & Supplement)

CHARACTER	Assigned for special survey	Machinery and Boilers
Date of last survey and of Periodical Surveys.		(including date of N.B. if any)
+ 100 A1		+ AMC
3,34		MS 4,30
S.S. 400 No. 3 4,30		BS 10,33
		CP 10,33

CARGO BATTENS NOT FITTED IN ...

Society's Freeboard (if assigned) as painted on Ship and now verified ... ins.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (state if on Fett). When put on, Month
Decks	State if Tanks now tested	Dblg. Plates under Sounding Pipes	Boats
Caulking of Decks	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Coamings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (State if wedges removed)
Beams & Fastenings	Cement or Asphalt (State which.)	Oil Bunkers	Sails
Outside Plating	Rudder	Scuppers	Equipment letter
" " in way of sidelights	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Breasthooks	Windlass	Hatches	Chain Locker
Transoms	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	" length (on board) mean diamr.
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" Rule length size
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Hawser & Warps
Transverses		Transoms Pointers, & Crutches ditto	Standing and Running Rigging
Floors		Timbers of Frame at openings ditto	
Keelsons		Ditto Ditto at other places ditto	
Stringers		Stringers, Clamps & Shelves ditto	
Inner Bottom Plating		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey;" "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptnD24, &c."

Survey Fee (per Section 20) £
Special Damage or Repair Fee (if any) (per Sec. 20) £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £

Fees applied for, £19
Received by me, £19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute
Withdrawn classed
Character Assigned
Write over insert
15/3/34

TUE. 12 MAR 1935

General Committee

Thursday, 14th March 1935

Decision of Classing Committee confirmed

Is Certificate required? If so, to be sent to

W1276-0103

© 2020

Lloyd's Register Foundation