

COPY FOR LONDON OFFICE.

Lloyd's Register of Shipping.



Port BAHIA BLANCA

31th August 1921

This is to Certify that I have

surveyed the tail shaft and stern tubes of the twin screw steamer "BAHIA BLANCA" at present in dry dock at Puerto Militar

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, ~~stating that all repairs~~

~~recommended by me have been completed to my satisfaction,~~ and

that I have Recommended that she be continued as classed in the Register Book and a fresh record be made of the tail end shaft having been seen 30-8-21

being fit to carry

H. C. Bruce

Acting Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register
Foundation