

16 MAY 1935

Chief Surveyors _____

Received from Chief Surveyors _____

L'S NAME "VALENTINO CODA" Report Lon. No. 102404a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/32.*)

of Survey _____ When due _____

The Donkey Boiler Survey became due 9,35.

The Genoa Surveyors now forward copies of letters received from the Owners to the effect that they have decided to withdraw this vessel from the Society's classification.

It is submitted the class of the vessel be withdrawn and three dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class
Insert ...

[Handwritten signatures and initials]
575736



© 2020

Lloyd's Register
Foundation

W1279-0072