

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME Steel Pad.Steamer. Messrs. Henry Robb, Rpt. Lth. No. 17628  
Ltd. - Yard No.141.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

ature of Survey.....



This vessel, after erection, has been dismantled for shipment to Singapore for re-erection, as in the case of the Sister vessel, Messrs.Henry Robb's Yard No. 140.

It is submitted the Singapore Surveyors be advised and requested to give the case the necessarybattention and forward a report on Form 8 when the survey has been completed.

A copy of the first entry report should be forwarded to the Surveyors.

The Surveyors, when forwarding their report, should state the name of the vessel, particulars of the shell riveting, equipment supplied and whether the inner surface of the bottom plating is protected with cement.

Li. 19/7/29

18.7.29.



© 2020

Lloyd's Register  
Foundation

W1287-0269